Ontario Branch Confidential Report

MULTIRISK SURVEY

Insured: INTRA COR. INC.

Location Surveyed: 20 QUEEN W ST TORONTO, ONTARIO M5H 3R3

Person Contacted: Lee Ann Gibbs Telephone Number: (416) 408-1200

> Policy Number: 4127271 AIS Reference: 70413142

Surveyed by: Paul Yeung Date of Survey: 1999.09.13

NOTE: The sole purpose of this report is to provide insurance pricing and underwriting information about the particular insured and location named. Only the person requesting this survey will receive a copy of the report, and IAO asks that it be kept strictly confidential. This report does not guarantee compliance with any standards or with any federal, provincial or municipal codes, ordinances or regulations. Tests of fire and other protection equipment have not been conducted or witnessed during this survey.

IAO reports, prepared in compliance with commonly accepted risk control standards existing at the time services are rendered, are developed from a survey of the premises and/or from data supplied by or on behalf of the Purchaser. IAO does not purport to list all hazards. While changes and modifications, referred to in the reports are designed to upgrade protection and loss prevention of the premises, IAO assumes no responsibility for management and control of these activities. IAO will not be responsible to the Purchaser for any loss or damages, whether consequential or other, however caused, incurred or suffered, as a result of the services being provided.

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

MULTIRISK - FIRE, LIABILITY AND BASIC CRIME

OCCUPANCY:

The insured is a tenant at this location. They have been in operation since 1997 and at this location for 2 year(s). They occupy 344 sq. m and are not the major occupant, having 15 employees. The premises are in good condition. The insured is interested in loss prevention, however there have not been any losses during the last 3 years.

* Occupancy Description (Insured / major tenant if insured is non-occupant)

Trading company with broker services.

* Other Classes of Occupants

Large office and retail complex with stores, numerous restaurants snd service industries.

* Undersirable Features

None

It is recommended that this location be resurveyed in 1 year(s).

BUILDING:

- * Built 1976 (est.) Height: Storey(s) (excluding basement) 36
- * Addition(s) 1979
- * There are no renovations.
- * Building condition Good
- * Area: Ground Floor 32921 sq. m Total (including basement) 395185 sq. m

BASIC CONSTRUCTION:

- * Walls 20% Fire Resistive Reinforced concrete 80% Non-combustible - Glass Panels
- * Floors (excluding basement) 100% Concrete
- * Roof 100% Concrete
 - Surface material(s) Tar and gravel
 - Roof replaced, unable to determine when.

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

INTERIOR FINISH:

- * Walls 100% non-combustible
- * Ceilings 100% non-combustible

BASEMENTS:

- * Number of basements 1
- * Total Area 40413 sq. m
- * Finished 50% Unfinished 50%

VERTICAL OPENINGS:

- * Stairs Fire rated enclosure
- * Elevators Fire rated enclosure
- * Escalators Protection open

MEZZANINE:

* Construction - Concrete

- * Occupancy Dining area of restaurant
- * Area 439 sq. m

OUTBUILDINGS: None

HEATING:

- * Heat exchange unit 100% Electric
 - Original installation.
 - Installation appears safe
- * Heating appliances All enclosed in a separate room
- * Combustible materials Not stored in this room at time of survey

* Chimneys:

- Other : None - Standard

ELECTRICAL:

- * Condition Good and appeared safe at the time of the survey.
- * Wiring Conduit, BX
- * Overcurrent protection Circuit Breakers.

* Electrical system - Original installation.

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

PLUMBING:

* Condition - Good at the time of the survey.

- * Piping is Copper
- * Plumbing Original installation.

EXPOSURES: (within 15m of the risk):

- * FRONT: TO TENANT Construction - Fire Resistive. Occupancy - Offices. Distance - 0 m Height - 35 storeys Protection - Automatic Sprinklers Grading - Light
- * LEFT: TO TENANT Construction - Fire Resistive. Occupancy - Offices. Distance - 0 m Height - 35 storeys Protection - Automatic Sprinklers Grading Light
- * RIGHT: TO TENANT Construction - Fire Resistive. Occupancy - Offices. Distance - 0 m Height - 35 storeys Protection - Automatic Sprinklers Grading - Light

* REAR: OPEN

MUNICIPAL PROTECTION:

- * The FUS Public Fire Protection Classification is 3
- * Responding (career) fire department Toronto
- * Distance from risk Less than 2.5 km
- * Access via Paved roads. Year-round.
- * The building itself is easily accesible to the fire department.
- * Two hydrants within 155m (standard)

PRIVATE PROTECTION at this location includes the following:

- * Standard extinguishers; Standard Standpipe & hose; Automatic sprinkler (The sprinkler system was neither tested nor evaluated during this survey, a sprinkler survey is available upon request)
- * Fire detection/alarm system Supervised Full Heat & Smoke
- * Guard service For building

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

MULTIRISK-LIABILITY

OCCUPANCY - GENERAL INFORMATION

- * Neighbourhood is predominantly commercial
- * Insured non-occupant building owner Area occupied 344 sq. m
- * 10% accessible to public. Public access is considered light
- * Gross revenue could not be determined at the time of the survey

PREMISES information at the time of this survey

* The following appeared to be SATISFACTORY:

Stairs, ramps, handrails; Floor surfaces & coverings; Wall & cellings; Inerior Lighting; Exterior Lighting; Emergency Lighting; Interior Housekeeping; Exterior Housekeeping; Washrooms, Sidewalks, Yards & Parking Lots; Snow & ice removal; Signs & Awnings; Fire exits; Fire alarms

ELEVATING DEVICES

* 8 Passenger elevators

- Current license is present.
- Maintenance contract Yes Company Owners responsibility
- * 2 Escalators
 - Current license is not present.
 - Maintenance contract Yes Company Owners responsibility

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

MULTIRISK-BASIC CRIME

NEIGHBOURHOOD:

- * Predominantly commercial
- * Stable
- * Best described as having a low crime rate

BUSINESS:

- * Description Trading and broker office
- * Hours of Operation Mon Fri 9am-5pm
- * Typical Stock Office furnitures, personal computers, records and files.
- * Target Stock Details Personal computers.
- * Smash and Grab exposure is low
- * There is no safe on the premises

GENERAL PROTECTION at the time of this survey:

* The following appeared to be SATISFACTORY:

Exterior Lighting, Interior Lighting, Roof Accessability, Target stock protection, Police Patrols

* Security Alarm System - None

PHYSICAL PROTECTION (TENANT or OWNER/OCCUPANT):

- * The exterior locks at this location are deadbolt
- * The windows are not barred

This report section is designed to provide basic crime information only. More detailed crime information can be obtained by ordering an Expanded Crime Supplement.

INTRA COR. INC. 20 ST QUEEN W; TORONTO, ONTARIO

MULTIRISK REMARKS/RECOMMENDATIONS

REMARKS:

* Fire, Liability & Basic Crime - The insured occupies part of the 38th floor of this large office building located in downtown Toronto, The office tower is part of the 'Eaton Center'. Insured is the president of this trading company. The building has a 24 hours security service. All elevators and stairways are shut off after business hours and are accessable to authorized people only. The building is well maintained, fire extinguisher is standard.

Insured was co-operative and is interested in loss control.

No recommendations made at this time.